

# THE BEDFORD CITIZEN



tight spaces



minimal  
overhead  
clearance



Very little space to move around & between the apparatus

Lack of storage



# plumbing & heating



## water damage



## decontamination



after a fire, the firefighters' turnout gear washer (r) & dryer (l) are installed on opposite sides of the apparatus bay

# Living quarters



office spaces



captain sullivan's office

the department's  
Administrative office



a communications center  
is in an open hallway